GAP SAFE INSTRUCTIONS



Gap Safe is easy to fit and very reliable when installed correctly. It is essential that these instructions are followed carefully.

PRODUCT DETAILS

Product code: Description:

05GC22 Gap Safe finger/arm protection cover

Height: 2n

To suit profile: 30 x 30mm and above

Minimum width: 50mm Maximum width: 150mm


Fixing Holes: $10 \times \emptyset$ 5mm (on each bracket)

Cover strip to hide fixings









TOOLS REQUIRED

Drill

Screw driver

Hacksaw

Fixings

INSTALLATION

- 1. Remove grey cover strips
- 2. Measure height of gate (cut guard to size if required)
- 3. Fit one end to the gate post first (pilot holes are required)
- 4. Fit other end to the gate frame
- 5. Slide in cover strips and check operation

Fixings are not supplied with this product.

Whilst every effort has been made to ensure the accuracy of the information supplied. F.H. Brundle cannot be held responsible for any errors or omissions. This product must only be employed for its original intended use. Any other use is wrong and potentially dangerous. Installation must be carried out in full compliance with current regulations. F.H. Brundle cannot be held liable for any damages resulting from wrongful, erroneous or negligent use.

Tel. 01708 25 35 45

